

11 5/14 split

DART AEROSPACE LTD	Work Order:	22601 A
Description: Fitting	Part Number:	D3216-3
Dwg: D3216 Rev. A	Qty:	10 50
Ref:		Page 1 of 1

Step	Location	Procedure	By	Date	Qty
1	DC	Issue Traveler	JF	05.03.02	50
2	PG	Issue P/O: <u>2004704</u> Email or Ship DXF file to vendor Laser Cut D3216-3 Fitting as per Dwg D3216 Material release note is required	U	05.03.11	50
3	RG	Receive and Inspect for transit damage Ensure material release note is attached	CL	05.04.01	50
4	QC6	Inspect dimensions as per Dwg D3216	SP	05/04/28	10
5	GA	Deburr if necessary. Tumble until parts have a polished finish.	SP	05/04/28	10
6	QC5	Inspect Finish	il	05.04.28	10
7	ST	Identify and Stock	U	05.04.28	10
8	AC	Cost / part <u>4.71</u>	JF	05.04.29	10
9	DC	Close W/O <u>4.75</u> Inspect Level 21	JF	05.05.03	10

Rev	Date	Change	Revised By	Approved
A	03.10.28	New Issue	KJ/RF	JF

RELEASED

04.01.03 RF